E000P-971092-01

Date: 12/03/97

# MODIFICATION REVIEW

For

## BEAMLINE PERSONNEL SAFETY SYSTEM

# ARGONNE NATIONAL LABORATORY ADVANCED PHOTON SOURCE EXPERIMENTAL FACILITIES

E000P-971092-01

# Modication Review for Beamline Personnel Safety System

PREPARED BY:	
Roy Emerson, Software Section Leader, APS/XFD/ISI	Date
REVIEWED BY:	
George Srajer, PSS Safety Committee Chairman, APS/X	Date XFD/SRI
John Stoffel, PSS Design Engineer, APS/XFD/ISI	Date
Nick Friedman, Interlock Systems Section Leader (acting	Date ), XFD/ISI
APPROVED BY:	
Jon Hawkins, Group Leader, APS/XFD/ISI	Date

## Modication Review for Beamline Personnel Safety System

# PSS Change Request 03 December 1997

## 1. PSS Change

#### Chain A:

This change will add a timer to the program to de-bounce the 60 PSI manifold pressure switch. The de-bounce period will initially be set at 3 seconds. However, the de-bounce period must not be longer than the timer period set for the shutter open operation.

#### Chain B:

Chain B is not affected and operates properly under this condition.

#### 2. Reasons for the PSS Change.

Experience has shown under actual operating conditions that there is a significant negative pressure spike which occurs during a shutter open operation. This momentary pressure drop is sufficient to cause a fault to be generated by the Chain-A PLC. This change is required to correct the program behavior to that which is expected and eliminate the spurious faults from occurring.

## 3. Extent of the PSS Change

This change will affect all Chain A Beamline code written or modified on or after 01 March 1998.

### 4. Method of Implementation

The changes will be applied using the existing Software Change Request mechanism as defined in the Software Configuration Management Procedures document E000P-921130-01 dated 03/25/96 for the Interlock Systems and Instrumentation Group.